10/008 636

Attorney Docket No.: 291958172US

I hereby certify that this correspondence is being deposited with the U.S. Postal Service with sufficient postage as First Class Mail in an envelope addressed to: Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450, on:

APR 11 2006 6

4/1/2006

By: Mulo Q 4 H

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

IN RE APPLICATION OF: GREGORY J. WILSON et al.

PATENT No.:

6,962,649

ISSUED:

NOVEMBER 8, 2005

FOR: CONTACT ASSEMBLIES, METHODS FOR MAKING CONTACT ASSEMBLIES, AND MACHINES WITH CONTACT ASSEMBLIES FOR ELECTROCHEMICAL PROCESSING OF MICROELECTRONIC WORKPIECES

EXAMINER: ARUN S. PHASGE

ART UNIT: 1753

CONF. No.: 3747

Certificate

APR 1 4 2006

of Correction

Request for Certificate of Correction under 37 C.F.R. §1.322 or §1.323

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Sir:

- 1. The applicant(s) requests a Certificate of Correction to correct errors in the above-identified patent, which are listed on the enclosed Form PTO/SB/44.
- 2. Any errors on the part of the applicant are of a clerical or typographical nature or are otherwise minor in character. None of the requested corrections would constitute new matter or require reexamination of the patent.
- 3. Source of Error(s) and Payment of Fee:
 - All of the errors listed on Form PTO/SB/44 are believed to be due to mistake on the part of the USPTO (37 C.F.R. §1.322). Accordingly, no fees are believed to be due.
 - At least one of the errors occurred due to applicant's mistake made in good faith (37 C.F.R. §1.323).
 - ☐ A check covering the fee under 37 C.F.R. §1.20(a) (\$100.00) is enclosed herewith.

- Please charge the fee under 37 C.F.R. §1.20(a) to Deposit Account No. 50-0665. This paper is provided in triplicate.
- Please charge any underpayment necessary for consideration of this paper to Deposit Account No. 50-0665.
- 4. Please send the Certificate of Correction to the undersigned at the address shown below.

Respectfully submitted, Perkins Coie LLP

Date: 7 Apr: 1 2006

Paul T. Parker

Registration No. 38,264

Correspondence Address:

Customer No. 25096
Perkins Coie LLP
P.O. Box 1247
Seattle, Washington 98111-1247
(206) 359-8000

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO: 6,962,649

DATED: November 8, 2005

INVENTOR(S): Gregory J. Wilson et al.

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 13

Line 50, insert new paragraph,

--a plurality of contacts projecting inwardly from the ring into the opening, the contacts comprising a dielectric element and a conductor having a first section in the dielectric element and a second section exposed relative to the dielectric element, wherein at least the second section of the conductor has an inert exterior, and wherein - --;

MAILING ADDRESS OF SENDER:

Perkins Coie LLP
PATENT-SEA
PO Box 1247
Seattle, WA 98111-1247

PATENT NO. 6,962,649

No. of additional copies

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Commissioner for Patents, Washington, DC 20231.